

# Questions

---

- ❑ 1. Reading Sensor values ?
    - ❑ Parametric functions
    - ❑ or specific function for each sensor.
    - ❑ Bounded curves
  - ❑ 2. Close loop (Monitoring+Traceability)?
    - ❑ Specific Nc\_Functions to be started depending on-line machine monitoring.
  - ❑ 3. Recorded Traceability Data with model in AP-238 ?.
    - ❑ **NO → Data to Log Files in FREE FORMAT.**
    - ❑ **YES → WHY ? And OPTIONS.**
  - ❑ 4. New nc\_variable Data Type ?
    - ❑ As for example: Date and Time.
-

# Questions

---

- 6. Other data??????? Which one?????:
    - Trace CNC Machine Events ?
      - Errors, warnings, alarms, manual/auto ....
    - Operator (authorization levels)
      - New Functions to Specify Operator levels required.
      - Level Definition.
    - Raw Materials, Workpiece: Serial Number or Lot Identifications ...
    - Tool data, Operator Data, Machine Data etc...
  - 7. For some of these data: Tool, operator, ...
    - Automatic Monitoring and logging changes?
-